



2021 SPILLWAY INSPECTION

- DEWATERED AND INSPECTED
- FOUND CONCRETE SPALLING AND WEAR AREAS THAT NEEDED PATCHING